





Land Title Act 1994; Land Act 1994 Form 21B Version 2			WARNING : Folded or Mutilated Plans will not be accepted. $\begin{bmatrix} \text{Sheet} & \text{of} \\ 2 & 6 \end{bmatrix}$				
700	C22CC0		Information may not be placed	in the outer margins.			
723633668			4. Lodged by				
	0 \$5,016.93 2024 14:51:48	(Dealing No.)					
			(Include address, phone number, email, reference, an	od Lodger Code)			
ı. Existing			(include dudiess, phone number, email, relevence, and codger code)  Created				
Title Reference		Description	New Lots	Road Secondary Interests			
51361811		Lot 1000 on SP344915	601-632 & 1000	New Rd Emts B-0 & LA			
		23556753 (Emt A on SP344915) 601-6	Lots to be Encumbered 1000 1000				
601-6  2. Orig Grant Allo 3. References: Dept File: Local Govt: Surveyor: 1068		Por 37v Orig	5. Passed & Endorsed:  By: SAUNDERS HAVILL GROUP PTY LTD Date: S/0/2024 Signed: Cac Designation: Endorsing Officer	6. Building Format Plans only.  Lectrify that:  * As far as it is practical to determine, no part of the building shown on this plan encroaches onto adjoining lots or road;  * Part of the building shown on this plan encroaches onto adjoining to or so on this plan encroaches onto adjoining to or on this plan encroaches onto adjoining to ots and road  Cadostral Surveyor/Director  * Date  * Date  * Date  * Date  * June Titles  * Photocopy  * Postage  * TOTAL  * SP344926  * SP344926  * SP344926			









## PERMANENT MARKS

PM	ORIGIN	BEARING	DIST	NO	TYPE
3-OPM	SP344915	42°16′25″	36-398	204997	

REFERENCE MARKS

<i>TO</i>	ORIGIN	BEARING	DIST
O Screw in Kerb	SP341894	66°49′	4.634
O Screw in Kerb	SP341894	93°02′	19-232
OIP	SP344915	13°39'20"	26.0
0IP	SP344915	76°58′20″	18·455
	O Screw in Kerb O Screw in Kerb OIP	O Screw in Kerb         SP34/894           O Screw in Kerb         SP34/894           OIP         SP3449/5	O Screw in Kerb SP341894 66°49′ O Screw in Kerb SP341894 93°02′ OIP SP344915 13°39′20″

Additional reference marks to be placed following road construction (see IS329472).

## REINSTATEMENT REPORT

- SP344926 is stage 6 of a multiple staged land development. SP344915 was stage 5, SP341894 was stage 4, SP341893 was stage 3, SP338112 was stage 2 and SP338081 was stage 1. IS308387 reinstated the external boundaries of the subject land, being Lot 3 on RP137533. See IS308387 for connection to datum All original corners on SP344926 are fixed by original monuments and / or dimensions vide SP344915, SP341894, IS323887, SP338112 and IS308387.

State copyright reserved.

SP344926